


## Reference body contacts—from self awareness (pd) tests


- for global data on procedure skill with compatible position and treatment technology-

0 = weight support centers for body at rest and feet at work



3 digit numbers =finger-hand contacts on body tissue and instruments

example: a\_235 instrument contact



← toe and foot contact vectors on switches at 2 and 5

← foot contact vector on handpiece regulator at 4



Full rest at horizontal

foot at work  
while seated

feet at rest contacts and space  
-no objects on the floor-